

---

# MiTek<sup>®</sup>

# SERVICE BULLETIN

---

Document ID:

## SB303

Title:

## Replacing the Motor Starter Overload Assembly (GE<sup>®</sup> to ABB<sup>®</sup>)

**Affected machinery:** BLADE<sup>™</sup> saw

**Distribution:** Customers upon order

**Applies to:** Customers with a faulty Contactor, Overload, Surge Suppressor, or Auxiliary Contact in their BLADE saw.

**Sensitivity:** Approved for customer use

---

**CAUTION:**

MiTek recommends printing this document in high resolution using color ink. Many of the graphics may be unclear and may create an unsafe condition if this recommendation is not followed.

MiTek Automation  
Phone: 800-523-3380  
Fax: 636-328-9218  
www.mitek-us.com

|                    |                  |
|--------------------|------------------|
| Part # and Rev.    | SB303            |
| Print Date         | 22 December 2025 |
| Effectivity        | All              |
| Revision Date      |                  |
| Revised By         |                  |
| Rev. Approved By   |                  |
| Orig. Release Date | 15 December 2025 |
| Orig. Created By   | P. Hopper        |
| Orig. Approved By  | A. Kara          |

## Purpose and Scope

This service bulletin instructs how to convert the overload assembly that controls the motor starter used in the BLADE saw from GE to ABB. The components of this overload assembly are the contactor, surge suppressor, overload, and auxiliary contact.

## Overview

### Parts Included

The parts included in this kit are shown in [Table 1](#). Please make sure all parts and supplies are present before starting the procedure.

Table 1: Parts in SB303KIT

| Quantity | Description               | Part #    |
|----------|---------------------------|-----------|
| 3 ft.    | Blue/White Jumper Wire    | 508006-10 |
| 1        | Surge Suppressor          | 509252    |
| 1        | Contactor                 | 509339    |
| 1        | Auxiliary Contact         | 509689    |
| 1        | Overload                  | 509879    |
| 1 Sheet  | Write-In Labels           | 694060    |
| 1        | Service bulletin document | SB303     |

If you have any questions, call MiTek Automation Support at 1-800-523-3380.





### Supplies Needed

- #2 Philips Head Screwdriver
- Voltmeter
- Wire Strippers
- Wire Snips

# Lockout/Tagout Instructions

## Electrical Lockout/Tagout Procedure

The lockout/tagout instructions for the electrical systems will be referenced as necessary in this document. Service Bulletin instructions start on [page 4](#).

|   |  |
|---|--|
|  | <div style="background-color: orange; text-align: center; padding: 5px;">  <b>WARNING</b> </div> <p><b>ELECTROCUTION HAZARD.</b></p> <p>All electrical work must be performed by a qualified electrician.</p> <p>Verify that all power to the machine has been turned off and follow approved lockout/tagout safety procedures before performing any maintenance.</p> <p>If it is absolutely necessary to troubleshoot an energized machine, follow NFPA 70E for proper procedures and personal protective equipment.</p> |
|---|--|

1. If applicable, close machine software and shut down the PC using the **Power > Shut down** method in Windows.
2. Engage an E-stop on the machine.
3. Turn the machine's disconnect switch to the Off position. This is usually required to open the main electrical enclosure's door.
4. Shut the power to the machine off at the machine's power source, which is usually an electrical service entry panel on the facility wall. One example of a locked-out power source panel is shown in [Figure 1](#).
5. Attach a lock and tag that meet OSHA requirements for lockout/tagout to the electrical service entry panel.
6. Open the door to the enclosure to which you need access. Use a multimeter to verify that the power is off.





Figure 1: Lockout/Tagout on the Power Source Panel



## Procedure

### Replacing GE Components with ABB Components



|   |   |
|---|---|
|   |  <b>WARNING</b>  |
|  | <p><b>MOVING PARTS CAN CRUSH AND CUT.</b></p> <p>Always verify that power to the machine has been turned off and follow approved lockout/tagout procedures.</p> |

1. Lockout/tagout the electrical and pneumatic systems of the machine using the [Lockout/Tagout Instructions on page 3](#).
2. With power locked out as previously described, open the top half of the saw's main electrical enclosure ([Figure 3](#)).

3. Locate the existing overload, contactor, side auxiliary contact, and front auxiliary contact ([Figure 2](#)).
- Note: Your machine's specific configuration within the electrical enclosure may vary. See [Figure 3](#) and [Figure 4](#) for examples.

Figure 2: Existing Electrical Components for Motor Starter





|   |  |
|---|--|
| Contactor   | Overload   |
|    |    |
| Side Aux Contact  | Front Aux Contact  |
|  |  |

Figure 3: BLADE Main Electrical Enclosure Example 1




Figure 4: BLADE Main Electrical Enclosure Example 2



4. Label the wires connected to the front auxiliary contact on terminals 97 and 98, then the wires connected to the overload on terminals 14/22 and 95NC. Use [Table 2](#) for reference.
  - Ensure each motor starter terminal block in the overload assembly has the correct labeling before being removed.

Table 2: Wiring Instructions


| Motor Starter Terminal Blocks |            | Wire Labels           |                         |                      |
|-------------------------------|------------|-----------------------|-------------------------|----------------------|
| Existing Blocks               | New Blocks | MS_2 (Waste Conveyor) | MS_3 (Incline Conveyor) | MS_4 (Outfeed Chain) |
| 1L1                           | 1L1        | 6L1                   | 6L1                     | 6L1                  |
| 3L2                           | 3L2        | 6L2                   | 6L2                     | 6L2                  |
| 5L3                           | 5L3        | 6L3                   | 6L3                     | 6L3                  |
| 21NC                          | 21NC       | 527                   | 528                     | 529                  |
| A1+                           | A1+        | Q17                   | Q18                     | Q19                  |
| NO23                          | NO23       | 50                    | 50                      | 50                   |
| 24                            | 24         | IN:13                 | IN:14                   | IN:15                |
| 97                            | 97         | 50                    | 50                      | 50                   |
| 98                            | 98         | 575                   | 575                     | 575                  |
| 2T1                           | 2T1        | 2T1                   | 3T1                     | 4T1                  |
| 4T2                           | 4T2        | 2T2                   | 3T2                     | 4T2                  |
| 6T3                           | 6T3        | 2T3                   | 3T3                     | 4T3                  |
| 14/22                         | 22NC       | 528                   | 529                     | 530                  |
| 95NC                          | 95         | 52                    | 52                      | 52                   |

5. Remove the existing overload, contactor, surge suppressor, and auxiliary contactor by determining each wire connected to them.



6. Mount the provided overload, contactor, surge suppressor, and auxiliary contactor and terminate the previously labeled wires using [Table 2](#).

Figure 5: ABB Replacement Components



7. Connect Terminal 96 to Terminal A2- using the provided white and blue jumper wire.
8. Dial the new overload to the appropriate value as indicated in [Table 3](#).

Table 3: New Overload Settings

| MS_2 (Waste Conveyor) | MS_3 (Incline Conveyor) | MS_4 (Outfeed Chain) |
|-----------------------|-------------------------|----------------------|
| 1.9 FLA               | 4.2 FLA                 | 1.9 FLA              |

9. Ensure all wires have been properly terminated by performing a torque check on each terminal screw.
10. Remove lockout/tagout devices and test the saw to ensure it functions without error.



## Appendix

### BLADE Saw Electrical Schematic Rev. D (For Reference Only)

Figure 6: Conveyors Power (Page 1)




Figure 7: Conveyors in Safety Circuit (Page 9)




Figure 8: Conveyor PLC Input Wiring (Page 15)




Figure 9: Conveyors PLC Output Wiring Start (Page 17)





Figure 10: Conveyors PLC Output Wiring Exit (Page 19)



**END OF SERVICE BULLETIN**